



Beaumont-Cherry Valley Water District

Phone: (909) 845-9581 Fax: (951) 845-0159

Email: info@bcvwd.org

<http://www.bcvwd.org>

March 15, 2018

Board of Directors

David Hoffman
Division 5

John Covington
Division 4

Daniel Slawson
Division 3

Claudeen Diaz
Division 2

Andy Ramirez
Division 1

Well 26 Pumping Facilities
Pumping Unit Repair Work
Notice Inviting Quotes for Well Repair

Subject: Well 26 Pumping Facilities, Pumping Unit Repair Work

To Whom It May Concern:

The Beaumont-Cherry Valley Water District (District) in soliciting bids for work related to repair of the District's existing Well 26 Pumping Equipment. This bid request also includes a provision for chemical treatment and re-habilitation of Well 26, which may be added to the scope of work upon completion of the initial well inspection video once the pumping unit is removed. Based upon recent well performance, the District does not feel that chemical re-habilitation will be necessary, but would like to secure a cost with this quote in case the video shows some unexpected issues.

These bids will be used to select the Project Vendor in conjunction with review of the Vendor's ability to meet the District's construction schedule. The completed Scope of Work-Fee Schedule will subsequently be used to negotiate a final scope of work related to repair of the Well 26 facilities.

Vendors shall submit sealed bids identified by the Subject Line Title: **"Well 26 Pumping Facilities, Pumping Unit Repair Work"** by 3:00 P.M. local time on **Thursday, March 29, 2018** to the Beaumont Cherry Valley Water District Office located at, 560 Magnolia Avenue, Beaumont, California 92223, telephone (951) 845-9581.

Please contact Director of Operations, Anthony Lara at tony.lara@bcvwd.org or at (951) 845-9581, or Assistant Director of Operations, James Bean at james.bean@bcvwd.org or at (951) 845-9581 to schedule a pre-bid tour or with any questions.

Time is of the essence for this repair work and the Vendor will be required to complete the work within 45 days from issuance on the Notice to Proceed. The 45 day completion schedule is based upon the presumption that existing pumping unit bowl assembly will be rebuilt.

Work required is described in the attached Exhibit A which includes a Scope of Work – Fee Schedule, project special requirements, technical specifications, and record information for Well 26. Quotes shall include all work listed on the attached Scope of Work-Fee Schedule included in Exhibit A. Any additional work identified in the Quotes that is not listed on the attached Scope of Work-Fee Schedule shall require written approval from the District.

bonds during final project negotiations based upon actual cost of any particular bond. In the event no bonds are required, Vendor shall provide a 30 month warrantee specified in the project Special Requirements included in Exhibit A.

Please call if you have any questions or require additional information.

Sincerely,

Anthony L. Lara
Director of Operations

ALL/al/jb

Attachments: **Draft Short Form Contract for Well 26 Pumping Unit Repair Work**
 Exhibit A-Well 26 Pumping Unit Repair Work

- **Scope of Work-Fee Schedule**
- **Well 26 Pumping Unit Repair Special Requirements**
 - **Appendix A:**
 - **Specification Section 11320 Vertical Turbine Pumping Unit Technical Specification**
 - **Specification Section 11330 Technical Well Rehabilitation of Well 26**
 - **Appendix B: Well 26 Site Plan Image and Photos**
 - **Appendix C: Well 26 Well and Pumping Unit Information**
 - **Appendix D: Well 26 SCE Pump Test Data**
 - **Appendix E: Maintenance Bond Example**